


Appendix B:

GUIDELINES for MEASURING AND DOCUMENTING EXTRAVASATION INJURIES



- With a pen or marker, draw around the circumference of the extravasation lesion.
- Measure the lesion at its greatest width and length (the 'x' and 'y' measurements, respectively, in the figure above). NOTE: length and width measurements should be perpendicular to each other.
- Document initial and subsequent measurements explicitly. Identify what was measured (*e.g.*, swelling, erythema, induration, ulceration, etc.) and when it was measured in relation to when extravasation occurred.